


Technical bulletin No.	<b>TB/005</b>	Issue No.	<b>002</b>
Date:	<b>13 March 2009</b>		
Associated bulletin No.	N/A	Issue No.	N/A
Eminox Part Number Ref.	<b>QM1136 (All variants)</b>		
Associated Part Number Ref.			
Distribution	<b>All workshops</b>		

**Subject: Changing ESI unit and wiring harness.**

The ESI (Electronic Service Indicator) consists of a central processor unit (CPU), wiring harness and sensor (see attached photo).



The CPU, wiring harness and sensor are matched together, therefore they **must not** be split.

If the ESI becomes faulty or is replaced under warranty the CPU, wiring harness and sensor must be replaced together and returned to Eminox. The replacement part will consist of all three items.

Swapping only part of the unit will invalidate your warranty.