

Technical bulletin No.	TB/002	Issue No.	001
Date:	30 January 2009		
Associated bulletin No.	N/A	Issue No.	N/A
Eminox Part Number Ref.	REBA 0006 (2.5ltr) REBA 0004 (28ltr)		
Associated Part Number Ref.	N/A		
Distribution	All workshops		

Subject: Satacen 3® Additive

The Eminox FBC system depends upon the use of Satacen 3® additive to aid regeneration of the filter. This prevents large accumulations of soot and eventual filter blockage.

Satacen 3® is a fuel borne catalyst developed by Innospec Inc who are one of the world's leading fuel treatment specialists. Without the Satacen 3® additive the system will not function correctly and excessive uncatalysed soot will build up on the filter. This will have an adverse effect on fuel consumption and over prolonged periods could cause damage to engine components.

- Under no circumstances should the vehicle be operated without Satacen 3® additive
- The vehicle should not be driven if the Satacen 3® tank is allowed to run dry.
- The FBC system will require priming (see link to manual below) if the Satacen 3® storage tank is allowed to run dry or the dosing system is repaired or replaced.
- **The use of Adblue in the system will also invalidate warranty as this will rust and destroy all metal components within the exhaust system.**
- **The use of Platinum Plus will invalidate your manufacturers' warranty.**

Eminox FBC Dosing System manual can be found here - <http://www.eminox.com/downloads/Eminox%20FBC%20Manual.pdf>